



Tel: +44 (0) 1942 265 700 Fax: +44 (0) 1942 670 788 www.intertek.com/consumergoods

FLAMMABILITY TEST REPORT

Report No.: LEHTX00880653 Date Received: 25/01/18 Date Tested: 07/02/18 Date Issued: 01/03/18

Company Name & Address: EASTMAN PERFORMANCE FILMS, LLC

575 MARYVILLE CENTRE DRIVE ST. LOUIS MO 63141-5713

USA

Contact Name:

N/A

Sample Details Reference

No.: Not stated Order No.: Not stated Style No .: Not stated Batch No .: Not stated Quality: Not stated Colour: Not stated Supplier: Not stated Intended Use: Not stated **Quoted Fibre Composition:** Not stated Retailer: Not stated **Buying Division:** Not stated

Sample Description: 6mm glass with 20 µm polyester installed.

Test Method	Pre Treatment	Flammability Performance Requirement	Result
FMVSS 302: 2011	None	Burn rate no greater than 4 inches per minute (102mm/min) as specified in BS AU 169a:1992 ISO 3795 1989	PASS

STEVEN OWEN ANDREW HALLETT CAROLE SPOWART SIMON CHEE

(Flammability Technician)

Report No.: LEHTX00900653 Page 1 of 2



(Operations Manager)



(Chemical Technologist)

(Flammability Team Leader)





Tel: +44 (0) 1942 265 700 Fax: +44 (0) 1942 670 788 www.intertek.com/consumergoods

FLAMMABILITY TEST REPORT

Test Specification

Test Method: FMVSS 302: 2011

Pretreatment: None

Conditioning: Prior to testing for a minimum of 24 hours at 50±5% RH & 21±2°C

Test Results

Specimen Number	First Marker Reached	Length Of Flame Travel From First Marker D (mm)	Burn Time From First Marker T (Seconds)	Burning Rate B (mm/min)
1	No	0.0	0.0	0.0
2	No	0.0	0.0	0.0
3	No	0.0	0.0	0.0
4	No	0.0	0.0	0.0
5	No	0.0	0.0	0.0

Average Burning Rate: 0.0 mm/min

Sample Size: 102mm x 356mm

Sample Thickness: ≤7mm on all samples

Direction relative to sample: Transverse

Composite Sample: Yes

Conclusion

On the basis of the tests carried out this sample meetsthe requirements of BS AU 169a:1992 ISO 3795 1989. PASS

This report is made solely on the basis of your instructions and/or information and materials supplied by you. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or willful misconduct.

Report No.: LEHTX00900653 Page 2 of 2



